## Therma-Hygrometer

max/min & alarm functions

- range of -49.9 to 69.9 °C & 20 to 99 %rh
- integral %rh & remote temperature probe

This therma-hygrometer simultaneously displays both the humidity and temperature in addition to indicating and recording the maximum and minimum readings.

The instrument measures both humidity and temperature over the range of 0 to 49.9 °C and 20 to 99 %rh utilising the internal sensors. Utilising the external temperature sensor the temperature range is extended to -49.9 to 69.9 °C.

The unit features a temperature alert alarm that will sound when the external remote temperature probe indicates the temperature is 0 °C or below. This feature is ideal for frost/freeze alert in horticulture and similar.

The unit is housed in an ABS case, measuring 20 x 65 x 97 mm, that incorporates a useful foldaway stand and a keyhole slot for hanging on a wall.

order code	description	
810-155	therma-hygrometer - alarm	



specification	temperature	humidity	
range	-49.9 to 69.9 °C	20 to 99 %rh	
resolution	0.1 °C/°F	1 %rh	
accuracy	±1°C	±5 %rh	
sensor type	thermistor	capacitance	
battery	1.5 volt AAA		
battery life	10000 hours		
display	dual custom LCD		
dimensions	20 x 65 x 97 mm		
weight	100 grams		

